



DiagnosticLink 8.23 SP3 Features

Service Diagnostics & Tools

2/11/2026



DiagnosticLink[®] 8.23 SP3 Release Features

General Updates and Enhancements

- DPF Light reset has been added for the purpose of resetting the sensor lights for ECONIC.
- A dialog has been added to set the values for MS time base and real time clock (RTC) for ECONIC.
- Added reference instrument cluster qualifier for Fifth Gen Cascadia Aerodynamic height control calibration (secondary air pressure instrument).
- Resolved an issue where the ESC panel (e.g., ABS02T and SBSPP01T) were not available for view in the log file.
- Resolved issue where the Bus monitor displayed negative timestamps.

(Previous Release) DiagnosticLink® 8.23 SP2 Features

General Updates and Enhancements

- Resolved issue where after programming CPC502T with DiagnosticLink 8.23, the parameters may be erased.

(Previous Release) DiagnosticLink® 8.23 SP1 Features

General Updates and Enhancements

- Resolved issue where the Relative Compression Test routine for 5th Gen Cascadia did not show.
- Resolved issue where the tool may crash due the following conditions:
 - Invalid character string error
 - Error in the clear faults process
 - If the ZenZefi database becomes corrupted.